
【原因・判断ポイント・発生工程】 S R 塗布乾燥後に、何らかの硬い物が強く接触し、擦れたことにより出来たもの(S R 塗布乾燥後工程)

【原因、判断要点、发生工序】SR 烘干后接触某种坚硬物体、摩擦而引起的(SR 烘干后工序)。

[Causes/processes involved/keys to judgment]

The defect is formed by a strong contact and abrasion on solder-resist surface by something hard after curing. (After solder resist coating and curing process)



2-1-2-4 SR 打痕/SR 的压痕/Dent on solder resist

【特徴】SR表面に凹み状の衝突打痕が残されている状態の欠陥

【特征】SR 表面有凹陷的碰撞压痕的缺陷。


[Characteristics] A dent by an impact is left on the solder resist surface.

【原因・判断ポイント・発生工程】 S R塗布乾燥後のハンドリング作業時に、不注意に何かにぶつけて出来たもの(SR塗布乾燥後工程)

【原因、判断要点、发生工序】涂布 SR 后的搬运作业时,不小心碰撞某种物体而引起的(SR 烘干后工序)。

[Causes/processes involved/keys to judgment]

The solder resist surface is carelessly hit by some object during handling after solder resist coating and curing. (After solder resist coating and curing process)



2-1-2-5 カバーレイ打痕/覆盖层的压痕 / Dent on coverlay

【特徴】カバーレイ表面に明確な打痕が認められる 欠陥

【特征】在覆盖层表面有明显压痕的缺陷。

[Characteristics] A dent of a definite shape is observed on the surface of coverlay



「コメント】 FPC 顕微鏡倍率× 「注釋」 FPC 显微镜倍率 × [Coments] FPC

Magnification: ×