

【特徴】SR 塗布面に白雲状の変色が見られる状態の欠陥

【特征】在SR 涂布面有白云形状的变化色的缺陷。

【Characteristics】Cloud-like discolouration appears on the coated solder resist surface.

【原因・判断ポイント・発生工程】SR 塗布の際、SR インクが塗布面に十分に充填されずに空隙が閉じ込められて出来たもの

【原因、判断要点、发生工序】在SR 涂布时，SR 油墨不能充分地填充涂布面，存在空穴而引起的（SR 涂布工序）。

【Causes/processes involved/keys to judgment】The filling of solder resist ink to the area to be coated is not sufficient and a void is left on the surface. (Solder resist coating process)

